



Product Change Notice

January 11, 2022

Ref: PCN 301-303-896-897

Dear Song Chuan Customer:

Please be advised that Song Chuan will be changing our 301, 303, 896, and 897 Relays as described below.

Song Chuan requests your approval for the change described below. Please let me know what the next steps should be.

Title of Change

301/303 Production Location Change, relay cover-marking change from ink printing to laser-etch and packaging change from trays to tubes.

896/897 Production Location Change only.

Part Number(s) Affected

Change:

301-1A-C-R1 U03 12VDC	Cover-marking, packaging and location change
301-1C-C-D1-U05-12VDC	Cover-marking, packaging and location change
301-1C-C-R1 U01 12VDC	Cover-marking, packaging and location change
301-1C-C-R1-U02-24VDC (30112)	Cover-marking, packaging and location change
301-1C-C-R1-U15-24VDC	Cover-marking, packaging and location change
301-1C-C-R1-U16-12VDC	Cover-marking, packaging and location change
301-1C-S-R1 12VDC	Cover-marking, packaging and location change
301E-1A-D-R1 U13 12VDC	Cover-marking, packaging and location change
303-1AH-C 12VDC	Cover-marking, packaging and location change
303-1AH-C-D1 12VDC	Cover-marking, packaging and location change
303-1AH-C-R1 12VDC	Cover-marking, packaging and location change
303-1AH-C-R1 24VDC	Cover-marking, packaging and location change
303-1AH-C-R1 U01 12VDC	Cover-marking, packaging and location change
303-1AH-C-R1 U04 24VDC	Cover-marking, packaging and location change
303-1AH-S-D1 12VDC	Cover-marking, packaging and location change
303-1AH-S-R1 12VDC	Cover-marking, packaging and location change
303-1AH-S-R1 U06 12VDC	Cover-marking, packaging and location change
896E-1AH-D-R1 U02 12VDC	Location change only
896E-1AH-D-R1 U66 12VDC	Location change only
896E-1CH-D-R1 U66 12VDC	Location change only
896H-1CH-C-R1 U03 12VDC	Location change only
896H-1CH-C-R1 U24 12VDC	Location change only



896H-1CH-C-U23 12VDC	Location change only
896H-1CH-S-R1-U25 12VDC	Location change only
897-1AH-C-R1 U03 12VDC	Location change only
897-1AH-C-R1 U06 12VDC	Location change only
897-1AH-C-R1-U09 12VDC	Location change only
897H-1AH-D-R1 U02 12VDC	Location change only
897H-1AH-D-R1-U66-12VDC	Location change only

Description of Change(s)/Modification(s)

Production location change from Xiamen, China to ChiaYi, Taiwan

Purpose

Part of Song Chuan's strategy to expand production to the new factory in ChiaYi, Taiwan.

Effects/Impact of Change

No change to relay fit, function, performance or specification/drawing. Old version and new version are interchangeable. No effect on cost or delivery.

Implementation timing

Production started in Q3 of 2021.

Respectfully,

Regional Sales Manager
Song Chuan USA

Email:

Please acknowledge your notification by signing below and emailing back to me. Thank you.

Acknowledged by: _____

Print Name: _____

Company Name: _____

Position / Department: _____

Date: _____